

● PRINTER RUSH ●
(PTO ASSISTANCE)


Application :	<u>10/038,942</u>	Examiner :	<u>N. PATEL</u>	GAU :	<u>2116</u>
From:	<u>R. MITCHELL</u>	Location:	<u>(IDC) FMF FDC</u>	Date:	<u>7/29/05</u>
Tracking #:			<u>6096882</u>	Week Date: <u>4/18/05</u>	

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449		<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS		<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM		<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW		<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW		<input type="checkbox"/> Other
<input checked="" type="checkbox"/> DRW	<u>4/1/02</u>	
<input type="checkbox"/> OATH		
<input type="checkbox"/> 312		
<input type="checkbox"/> SPEC		

[RUSH] MESSAGE:	<u>ATTENTION CHIEF DRAFTS PERSON</u>
	<u>'FIG. 3' LABEL MISSING ON DRAWINGS</u>

[XRUSH] RESPONSE:	
	<u>Drawings Corrected</u>
	INITIALS: <u>gjt</u>

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.
REV 10/04



The Output Mask is Used in Where Support is Needed for Domain to be in Reset While the Domain is not. It Prevents output_pulses from Occuring Reset of the input flip-

FIG.3